Hood River County School District – 2016 Bond Projects

Bond Projects Report November 2019





Cascade Locks Elementary School





Cascade Locks Elementary School





Cascade Locks Elementary School





May Street Elementary School







May Street Elementary School






May Street Elementary School



- Winterization of Phase 2
- Play Fields Seed vs. Sod
- Building Management System Heating & Cooling
- ADA Ramps



| onstruction, L.L.C. | | | | | Date: 10/15/19 | | | |
|-------------------------------|---|--------------------------|--------------------|--------------|---------------------------------------|-------------------------------------|----------------|---|
| Spec Sec # | # Description GENERAL CONDITIONS | Quantity | Unit Cost (Public) | U/M | Total Amount | VE:8/15/2019 | 7/29/2019 | |
| <i>01000</i> 020000 | General Conditions EXISTING CONDITIONS | 6 | 38716 | LSUM | 232296 | 232296 | 232296 | 6 month project |
| 022000 024000 | Assessment (Survey) | 1 | 2500 | LSUM | 2500 | 2500 | 2500 | |
| 024000 | Demolition Admin Conversion Demo | | 10000 | LSUM | 10000 | 10000 | 10000 | |
| | New Lift Area Demo Breezeway Ceiling Demo | 0 | 15000 3.5 | LSUM LSUM | 15000 | 0 | 5750.5 | |
| 028000 | Existing slab Demo Facility Remediation | 2963 | 9.5 | SF | 28148.5 | 28148.5 | 43757 | any asbestos? |
| 030000 <i>033000</i> | CONCRETE Cast in Place Concrete | | | | | | | |
| 00000 | SOG addition w/ Ftgs New Lift Area Concrete | | 59380 9378 | LSUM LSUM | 59380 9378 | 45213 | 87150 | Leave breezeway slab as is |
| 034000 | Exterior Slab and Stairs (Back Exit) Precast Concrete - slabs | | 18 | LSOW | 6066 | 6066 | 7280 | |
| | Precast Panels | 67 | 30 | SFCA | 2010 | 2010 | 1800 | |
| 035000 | Cast Decks and Underlayment Gypsum Underlayment | 1643 | 4.5 | SF | 7393.5 | 7393.5 | | Gyp overlay existing breezeway slab |
| 040000 <i>047000</i> | MASONRY Manufactured Masonry | | | | | | | |
| 050000 | Brick Veneer METALS | 376 | 45 | SFCA | 16920 | 16920 | 31500 | |
| 052000 | Metal Joists Assembly - Metal Joists and Deck | | 35 | SF | 0 | 0 | 07745 | VE to wood |
| 054000 | Cold Formed Metal Framing | | | | | | | |
| 055000 | Metal Stud Walls Metal Fabrications | | 16 | SFCA | 0 | 0 | | VE to wood |
| 060000 | Steel Stairs/Handrails/Guardrails WOOD & PLASTICS | 0 | 750 | LF | 0 | 0 | 19500 | no more stairs to old gym |
| 061000 | Rough Carpentry ADA lift area framing | 1 | 2500 | LSUM | 2500 | | | |
| | Open Web Roof Joists with Decking Wall Sheathing | 2089 | 15 | SF SFCA | 31335 10143 | 31335 10143 | 0 | |
| 070000 | Wall Framing | | 9.5 | SFCA | 32119.5 | 32119.5 | 0 | i.w. 213'x12 + e.w. 55'x15' |
| 070000 071000 | THERMAL AND MOISTURE PROT Dampproofing and Waterproofing | | 5000 | LSUM | 5000 | 5000 | 5000 | |
| 072000 072500 | Thermal Protection (and acoustical) Weather Barriers | | 1.5 | SCFA | 7231.5 | 7231.5 | 7231.5 | |
| 074000 | Tyvek System Roofing and Siding Panels | 636 | 2.5 | SFCA | 1590 | 1590 | 5362.5 | |
| 075000 | Sheetmetal Siding Membrane Roofing | 260 | 20 | SFCA | 5200 | 5200 | 2240 | 5'tall x 52 feet |
| 076000 | PVC (60mil) w/ Polyiso crickets Flashing and Sheetmetal | 2089 | 16 | SF | 33424 | 33424 | 40112 | |
| | Parapet Coping/ reglet and counterflash | 155 | 35 | LF | 5425 | 5425 | 6000 | |
| 080000 081000 | DOORS AND WINDOWS Doors and Frames | | | | | | | |
| | Interior WD+HM frame+hardware (FOB) Add for sidelite to above | 10 5 | 1325 400 | EA EA | 13250 2000 | 9275 2000 | 0 | |
| 084000 | Entrances, Storefronts and Curtain Walls Exterior Storefront | 486 | 90 | SFCA | 43740 | 43740 | 36900 | |
| | Exterior Storefront Doors/HW Interior Storefront | 6 | 3000 70 | EA SFCA | 18000 12530 | 12000 12530 | 12000 0 | 7' tall x 21' and (2) 4'x4' window |
| 090000 | Interior Storefront Door/HW FINISHES | | | EA | 10000 | 10000 | 30000 | |
| 092000 | Plaster and Gypsum Board | | | | | | | |
| | New ADA lift area drywall walls (hang, tape, texture) | | 3.5 | SF SFCA | 2000 20779.5 | 20779.5 | 33747 | |
| 095000 | Ceilings Acoustical Ceilings | 3464 | 6 | SF | 20784 | 20784 | 33150 | includes admin conv. And staff conv., leave breezeway ceiling as |
| 096000 | Flooring Carpet Tiles | 5284 | 4.25 | SF | 22457 | 22457 | 23481.25 | includes admin conv. And staff conv. And breezeway and addition |
| | New ADA lift area Rubber Base 4" | | | SF LF | 850 2282 | 2282 | 19284 | 235' for admin/staff conv. |
| 099000 | Sheet Linoleum/Marmoleum Painting and Coating | 211 | 7 | SF | 1477 | 1477 | 0 | |
| 033000 | Exterior Sealing New ADA lift area | | 2.5 | SF SF | 940 600 | 940 | 1350 | |
| | Interior Painting | | 1.5 | SF | 12430.5 | 12430.5 | 16683 | includes admin conv. And staff conv., leave existing exterior brick |
| 100000 101000 | SPECIALTIES Information Specialties | | | | | | | |
| | room signage Marker/Tackboards | | 75 900 | EA EA | 450 5400 | 450 5400 | 450 12000 | includes admin conv. And staff conv. |
| 104000 | Safety Specialties FE/Cabinets | | 350 | EA | 700 | 700 | 700 | |
| 107000 | Exterior Specialties Exterior Vertical and Roof Expansion Joint | | 100 | LF | 4900 | 4900 | 0 | |
| 110000 | EQUIPMENT | 43 | 100 | Li | 4900 | 4300 | Ū | |
| 120000 123000 | FURNISHINGS Casework | | | | | | | |
| | Custom Lower Cabinets Solid Surface Countertops | | 250 70 | LF SF | 12255 7980 | 12255 7980 | 17845 11620 | |
| 130000 | SPECIAL CONSTRUCTION | | | | 7900 | 7900 | 11020 | |
| 144000 | CONVEYING EQUIPMENT Lifts | | | | | | | |
| 210000 | Wheel Chair Lift FIRE SUPPRESSION | 1 | 30000 | EA | 30000 | 30000 | 40000 | 2 level |
| | Fire Sprinklers | 4011 | 6 | SF | 24066 | 24066 | 24900 | Believe the canopy sprinklers need to be modified if they exist. |
| 220000 | PLUMBING School Building | 4150 | 5.45 | SF | 22617.5 | 22617.5 | 22617.5 | |
| 230000 | HVAC HVAC systems | | | | | | | |
| | Office Building (Rooftop, Multizone) Radiant Heating in breezweay | | 5175 7500 | TON EA | 56925 37500 | 56925 | 55200 | |
| 260000 | ELECTRICAL | | | | | (0500 | 45.770 | Main addition and admir A-d-t-ff |
| 270000 | COMMUNICATIONS | 3782 | 28 | SF | 105896 | 105896 | 154700 | Main addition and admin conv. And staff conv., leave breezeway |
| 280000 281000 | ELECTRONIC SAFETY & SECURITY Access Control | | | | | | | |
| 310000 | Door Access Control EARTHWORK | 3 | 7000 | EA | 21000 | 21000 | 21000 | |
| 312000 | Earth Moving | 454 | 25 | CV | | | | |
| | General Excavation and Embankment New ADA lift area earthwork | 1 | 25 10000 | CY LSUM | 3850 10000 | 3850 | 3850 | |
| 320000 | Continuous Footing Excavation/Backfill EXTERIOR IMPROVEMENTS | 284 | 8 | LF | 2272 | 2272 | 2272 | |
| 321000 | Bases, Ballasts, and Paving 6" Agg Base | 2507 | 2 | SF | 5014 | 5014 | 2200 | leave breezeway as is |
| 330000 | UTILITIES | | | J. | 5014 | 5014 | 6300 | 5.0020114, 40 10 |
| 334000 | Stormwater Utilities 4" to 8" | | 26 | LF | 1300 | 1300 | 1300 | |
| | Catch Basins ALTERNATES | 1 | 1100 | EA | 1100 | 1100 | 1100 | |
| | Restroom Refresh Scope | | 45000 105000 | LSUM LSUM | 45000 120000 | | | |
| | Courtvard Scope Addition (incl optional snowmolt) | | | | 120000 | | | |
| | Courtyard Scope Addition (incl optional snowmelt) Wall Mount ADA retrofit at existing stairs | | | | | | | |
| | Wall Mount ADA retrofit at existing stairs Subtotal | | | | 1,225,406 | 958,436 | 1,256,810 | |
| | Wall Mount ADA retrofit at existing stairs | 1.00% 5.00% 10.00% | | | 1,225,406 14764 73820 147639 | 958,436 11547 57737 115474 | | builders risk is by owner |





Conceptual Estimating: HRCHS CTE Renovation/Addition

Date: 10/31/19

| Group | | Description | | Unit Coet (Bublish | 11/85 | Total Amount | 8/45/2040 | 7/20/2040 | notes |
|------------|-------------------------|--|-----------------|--------------------|------------|--------------------|--------------------|--------------------|---|
| Group 1 | | Description GENERAL CONDITIONS | | Unit Cost (Public) | | Total Amount | 8/15/2019 | 7/29/2019 | notes |
| 2 | 01000 020000 | General Conditions EXISTING CONDITIONS | 8 | 38410 | LSUM | 307280 | 307280 | 307280 | 8 month project |
| - | 024000 | Demolition | | 04.50 | 1.61 | | | | |
| | | Demolition (Structural & Non-structural) | 1 | 81,591 | LSUM | 81591 | 7000 20000 | 15000 20000 | |
| | 028000 | Flooring Demo Facility Remediation | 0 | 1.25 | SF | 0 | 12735 | 12735 | any asbestos? |
| 3 | 030000 | CONCRETE | | | | | | | any descented: |
| | 033000 | Cast in Place Concrete Structural Concrete | 1 | 86,140 | LSUM | 86140 | o | 13800 | |
| | | SOG bus shelter | | ., | | incl | 0 | 21000 | |
| | | SOG pourback @ lift Ftg/Stem @ new exterior wall | | | | incl incl | 10925 8625 | 10925 8625 | |
| 4 | 040000 <i>042000</i> | MASONRY Unit Masonry | | | | | | | |
| | 042000 047000 | Manufactured Masonry | | | | | | | |
| 5 | 050000 | block veneer (CMU size) METALS | 0 | 24 | SFCA | 0 | 0 | 48960 | |
| | 052000 | Metal Joists | 625 | 40 | CF. | | | | metals storage roof and new server-de |
| | 055000 | Assembly - Metal Joist and Deck Metal Fabrications | | 18 | SF | 11250 | 6500 | | metals storage roof and new covered area |
| e | 060000 | Columns, Ledger, lintels and beams WOOD & PLASTICS | 1 | 20000 | LSUM | 20000 | 20000 | 35000 | Avoid the major structural modification at bearing wall |
| Ü | 061000 | Rough Carpentry | | | | | | | |
| | | Open Web Roof Joists with Decking Wall Sheathing | | 25 3 | SF SFCA | 15000 16200 | 9000 13740 | 9000 17880 | Bus Shelter |
| 7 | 070000 | Wall Framing | | 9.5 | SFCA | 95190 | 82963.5 | 101887.5 | |
| ′ | 070000 <i>072000</i> | THERMAL AND MOISTURE PROT Thermal Protection (and acoustical) | 0 | 1.5 | SCFA | 0 | 0 | 33487.5 | Assume upgrade to roof insulation too |
| | 072500 | Weather Barriers Tyvek System | 5400 | 1.5 | SFCA | 8100 | 9160 | 6000 | |
| | 074000 | Roofing and Siding Panels | | | | | | | Outdoor covered motel starage has shaller and annual |
| | | Sheetmetal Roofing Sheetmetal Siding | | 14 10 | SF SFCA | 17150 48800 | 14000 45800 | | Outdoor covered metal storage, bus shelter and cover area Bus Shelter and exterior wall and cover area |
| | 075000 | Membrane Roofing PVC (60mil) w/ Polyiso crickets | | 16 | SF | 0 | o | 7360 | New Addition |
| | 076000 | Flashing and Sheetmetal | | | LF | | | | |
| 8 | 080000 | Parapet Coping DOORS AND WINDOWS | | 25 | Lr | 0 | 0 | 2500 | |
| | 081000 | Doors and Frames WD+HM frame+hardware (FOB) | 0 | 1325 | EA | 0 | 0075 | | |
| | | HM+HM frame+hardware (FOB) | 18 | 1325 2725 | EA | 49050 | 9275 5450 | 0 | |
| | | Add for sidelite to above HM frame (to replace interior storefront) | | <u>400</u> 35 | EA SFCA | 6400 8400 | 3600 | 0 | |
| | 083000 | | | | | 2.30 | | | |
| | 083000 | Specialty Doors and Frames overhead doors relocate | | 2000 | EA | 4000 | 13500 | 27000 | |
| | 084000 | New OH door w/ man door Entrances, Storefronts and Curtain Walls | 1 | 5000 | EA | 5000 | | | |
| | | Exterior Storefront Exterior Storefront Doors/HW | | 90 3000 | SFCA EA | 0 | 0 | 32400 18000 | 45LF x 8' |
| | | Interior Storefront | 0 | 60 | SFCA | 0 | 0 | 24840 | 69LF x 6' |
| | 085000 | Interior Storefront Door/HW Windows | 0 | 2500 | EA | 0 | 0 | 17500 | |
| | 088000 | Aluminum Windows Glazing | 256 | 70 | SFCA | 17920 | 25200 | | |
| | | relites | 324 | 25 | SFCA | 8100 | | | |
| 9 | 090000 <i>092000</i> | FINISHES Plaster and Gypsum Board | | | | | | | |
| | | drywall walls (hang, tape, texture) | 10180 | 3.5 | SFCA | 35630 | 36841 | 38144 | |
| | 095000 | Ceilings Acoustical Ceilings | | 6 | SF | 9174 | 18000 | 35448 | Just Patch back most areas and some new |
| | 096000 | New Tiles Flooring | 2172 | 3 | SF | 6516 | | | |
| | | VCT Rubber Base 4" | | 3.5 2.5 | SF LF | 472.5 3125 | 2904 | 2904 | |
| | | Sheet Linoleum/Marmoleum | 0 | 7 | SF | 0 | 36365 | 41356 | |
| | | Polished Concrete (400 grit) Seal/Stained Concrete | | | SF SF | 28874.5 0 | 0 6153 | 18190 | |
| | 099000 | Painting and Coating Exterior Sealing | | 1.5 | SF | 0 | 0 | 3600 | |
| | | Paint Existing Deck | 4642 | 2 | | 9284 | | | |
| 10 | 100000 | Interior Painting SPECIALTIES | 10180 | 1 | SF | 10180 | 27102 | 27102 | |
| | 101000 | Information Specialties | 0 | 75 | EA | 600 | 000 | 600 | |
| | | room signage Marker/Tackboards | | 75 900 | EA | 5400 | 600 5400 | | One 4x8 marker and 2 - 4x4 tack |
| | 102000 | Interior Specialties Wood Bench | 19 | 50 | LF | 950 | | | |
| | 105000 | Storage Specialties Lockers | | 350 | LF | 18900 | | | |
| 11 | 110000 | EQUIPMENT | | 000 | | 16900 | | | |
| 12 | 120000 123000 | FURNISHINGS Casework | | | | | | | |
| | 123000 | Custom Upper Cabinets | | 185 | LF | 13135 | | | |
| | | Custom Lower Cabinets Plastic Laminate Countertops | | 225 60 | LF SF | 19800 10560 | 32250 15000 | 32250 15000 | |
| 13 | 130000 | Plam tables SPECIAL CONSTRUCTION | | 62 | SF | 0 | | | Allied/Ag tables at built in counters |
| 13 | 140000 | CONVEYING EQUIPMENT | | | | | | | |
| 21 | 210000 | FIRE SUPPRESSION | E445 | 4 | SF. | 6.170 | 00.177 | | leave existing interess as is with modifications to account |
| 22 | 220000 | Fire Sprinklers PLUMBING | 5445 | 4 | SF | 21780 | 20447.3 | 41245 | leave existing int.space as is with modifications/new in shop |
| 22 | 230000 | School Building HVAC | 20 | 3000 | Fixture | 60000 | | | |
| 23 | 230000 | HVAC systems | | | | | | | |
| 26 | 260000 | Office Building (VRF w/ERV for OSA req) ELECTRICAL | 16 | 5500 | TON | 88000 | 88000 | 176000 | leave existing int. space as is with modifications/new in shop |
| | | Electrical Systems (incl low volt/access control pathways) | 5445 | 26 | SF | 141570 | 145652 | 293800 | leave existing classroom as is with modifications/new in shop |
| 27 28 | 270000 280000 | COMMUNICATIONS ELECTRONIC SAFETY & SECURITY | | | | | | | |
| 20 | 280000 281000 | Access Control | | | | | | | |
| 31 | 310000 | Door Access Control EARTHWORK | 0 | 7000 | EA | 0 | 14000 | 21000 | |
| | 312000 | Earth Moving | 440 | 50 | 011 | | | | Assume I'A is El des |
| | | General Excavation and Embankment Dig for plumbing | 115 | 50 20 | CY LF | 5800 2300 | 2700 | | Assume lift is 5' deep |
| 32 | 320000 | Continuous Footing Excavation/Backfill EXTERIOR IMPROVEMENTS | | 15 | LF | 4770 | 2544 | 2544 | |
| 32 | 321000 | Bases, Ballasts, and Paving | | | | | | | |
| | 323000 | 6" Agg Base Site Improvements | 1497 | 2 | SF | 2994 | 2994 | 2994 | |
| 20 | | Chain Link Fencing w/ gates | 470 | 10 | SCFA | 4700 | 4700 | 4700 | 47LF |
| 33 | 330000 | UTILITIES | | | | | | | |
| | | Subtotal Insurance | 1.00% | | | 1,310,086 15784 | 1,099,054 13242 | 1,631,380 18538 | builders risk is by owner |
| | | Fee | 5.00% | | | 78921 | 66208 | 92692 | Deligation to by Owner |
| | | Contingency Bond | 10.00% 1.00% | | | 157842 15784 | 132416 13242 | 92692 18538 | |
| | | <u> </u> | | | | | | | |
| | | Grand Total | | | | \$1,578,417 | \$1,324,162 | \$1,853,840 | <u> </u> |